

TA 424 S83



NOTES ON THE PROPOSED INTOOD FRENCH SYSTEM OF TREATING PO. BOUCHERIX PROCESS FOR USE IN FOREST. O. T. Swan







(This data is not for publication without consent of the Forest Service.)

UNITED STATES DEPARTMENT OF AGRICULTURE FOREST SERVICE

NOTES ON THE PROPOSED INTRODUCTION OF THE FRENCH SYSTEM
OF TREATING POLES BY THE BOUCHERIX PROCESS FOR
USE ON THE NATIONAL FORESTS

and results of treating poles in several European poun-

1910, the subject was taken up-with Assistant District

Curanter of District Sentence By

O. T. Swan

The Bounterie process aims to fill the sapport

of aux captible apecies with a water solution of an anti-

about by supportant the original control of the con

Forest Assistant, Forest Service
March, 1911.

SET Smith, who inne-

12/29/20

noitabildug to ton ol atab sign)
jackof ent to the smoot signific

davamintada so tudamidada armam anatum adilima semida

izan se podisti ant so univergorom absoldad die me area not efficie riskanot em et senos encender e efficies ingginal pur so ses

Agric.-Forestry. Main Library

isva it 10 adfvins faafot väkülütas faarot fill välist

APPLICABILITY OF THE BOUCHERIE SYSTEM OF POLE PRESERVATION TO THE NATIONAL FORESTS

By O. T. Swan

Forest Assistant, Forest Service

Introduction.

in 1910 the writer made a study of the methods and results of treating poles in several European countries. The Boucherie process in common use in France seemed applicable to certain conditions in the United States and especially to the National Forests. In june 1910, the subject was taken up with Assistant District Forester of District 5, Mr. C. Stowell Smith, who immediately saw the possibilities of the method and made plans to test it in California. Later the experiments were deferred until the summer of 1911.

The Boucherie process aims to fill the sapwood of susceptible species with a water solution of an antiseptic salt, generally copper sulphate. This is brought about by applying the solution under a gravity pressure of 20 to 30 feet to the butt of a freshly cut pole. The antiseptic solution is thus forced from end to end of the pole.

APPLICABILITY OF THE BOUCHERIE SYSTEM OF POLE

By O. T. Swan

Forest Assistant, Forest Service

0 25 27

Introduction.

CO.

· H

in 1910 the writer made a brudy of the methods and results of treating poles in several European downtries. The Boucherie process in common use in France accured applicable to certain conditions in the United States and especially to the Mational Forests. In june 1910, the subject was taken up with Assistant District F. Mr. C. Stewell Smith, who immediately new the possibilities of the method and made plans to test it in California. Later the experiments were deferred until the summer of 1911.

The Boucherie process aims to fill the sapwed of susceptible apecies with a water solution of an anti-septic salt, generally dopper sulphage. This is brought about by applying the solution under a gravity pressure of 20 to 30 feet to the butt of a freshly out pole. The antiseptic solution is thus forced frem end to end of the pole.

General.

General.

In France the telephone and telegraph lines are in charge of the federal department of Posts and Telegraphs. From 250,000 to 300,000 poles per year are consumed in the Government lines and practically all of these are treated with a solution of copper sulphate under what is known as the Boucherie process. Other preservatives are used to a comparatively small extent for experimental purposes.

Previous to 1874, creosote was used to a great extent for treating poles in France. Since that time the use of copper sulphate has become general for the treatment of poles. Creosote was objected to because the workmen found it very disagreeable and considerable trouble with them resulted. The men sometimes refused to hamle the timber except at high wages. There was also trouble because creosote contaminated the water supply near places where treated timber was set.

The Boucherie process is not a revival of a dead process, but is is a method which has been in continuous and large use in Europe since it first became generally known. Today about one-third of the poles used in Germany and practically all of those used in France are treated under variations of this system. It can not be used in any climate or with any species of timber. For its

wolution must be very pare.

Bemeral.

In France the telephone and telegraph lines are in charge of the federal department of Posts and Telegraphe. From 250,000 to 500,000 poles per year are consumed in the Government lines and practically all of these are treated with a solution of copper sulphate under what is known and the Boucherie process. Other preservatives are used to a comparatively small extent for experimental purposes.

Previous to 1874, creosote was used to a great extent for treating poles in France. Since that time the use of copper sulphete has become general for the treatment of poles. Oreceote was objected to because the workness found it very disagreeable and considerable trouble with them resulted. The men sametimes befused to handle the timber except at high wages. There was also trouble because creosote contaminated the water supply near places where treated timber was set.

The Boucherie processis not a revival of a dead process, but is is a method which has been in continuous and large use in Europe since it first became generally known. Tosay about one-third of the poles used in Germany and practically all of those used in France are treated under variations of this system. It can not be used in any climate or with any species of timber: Foreits.

essary and a species of timber largely sapwood. The system has the advantage of treating the entire pole at a very low cost. Further, only a relatively inexpensive equipment to do this work is required and after it is once in operation very little technical supervision is necessary. Copper sulphate is inexpensive and the amount necessary to treat a large number of poles can be very cheaply transported in the crystal form. For this reason the method seems well adapted to certain parts of the United States and especially some of the National Forests.

It will be necessary to make a number of experiments to find out just what success may be had in treating different American species since nothing has been attempted previously along this line.

Advantages and Disadvantages of the Use of Copper Sulphate.

A solution of copper sulphate is the solution commonly employed in this process. Among the disadvantages of the use of copper sulphate is the fact that it attacks iron, resulting in the formation of iron sulphate which destroys organic matter, but other metals which will not be attacked by the sulphate may be used in the equipment of the plant. The preservative action of copper sulphate is weakened by the presence of alkaline salts in the soil in which the poles are set. It is dissolved by rain water charged with carbonic acid. The water used in mixing the solution must be very pure.

ensary and a species of timber largely sapwood. The system has the advantage of treating the entire pole at a very low cost. Further, only a relatively interpensive equipment to do this work is required and after it is once in operation very little technical supervision is necessary. Copper sulphate is inexpensive and the amount necessary to treat a large number of poles can be very cheaply transported in the crystal form. For this reason the method seems well a upted to certain parts of the United States and especially some of the National Forests.

It will be necessary to make a number of experiments to find cut just that success may be had in treating different American apecies since nothing has been attempted previously along this line.

Advantages and Disadvantages of the Use of Copper Sulphate.

A solution of copper sulphate is the solution commonly employed in this process. Among the disadvantages of the use of copper sulphate is the fact that it attacks iron, resulting in the formation of iron sulphate which destroys organic matter, but other metals which will not be attacked by the sulphate may be used in the equipment of the plant. The preservative action of copper sulphate is weakened by the preservative action of copper sulphate in which the poles are set. It is dissolved by rain water charged with carbenic acid. The water used in mixing the solution must be very pure.

inexpensive preservatives may be employed. Since they are used in solution the transportation of quantities sufficient for the treatment of a large number of poles is relatively sheap. The preservative for many poles is easily and cheaply stored. It is claimed that copper sulphate decreases the combustibility of the wood. The presence of the copper in treated wood is often apparent at sight, and is also proved by very easy and certain chemical tests. The equipment is relatively cheap, but a small amount of labor is required, and very little technical supervision is necessary.

Plant Required.

The plant necessary for treating poles by the Boucherie process consists of a tank of the copper sulphate solution raised on a tower or other support at a sufficient elevation to force the solution through the poles after a suitable apparatus communicating with the elevated tank has been connected at the butt of each pole. In order to supply the reservoir solution tank on the tower with additional quantities of the preservative, a mixing tank is set up at the foot of the tower. Here the proper proportions of pure water and copper sulphate are mixed, forming the treating solution. A hand pump or one run by an electric motor is generally installed to carry the solution

pole to the other it is necessary to use an inexpensive

The Boucherie system has the advantage that
inexpensive preservatives may be employed. Since they
are used in solution the transportation of quantities;
sufficient for the treasportation of quantities;
sufficient for the treatment of a large number of poles
is relatively eneapy. The preservative for many polesis
easily and chesely stored. It is claimed that copper
sulphate decreases the combustibility of the wood. The presence of the copper in treated wood is often apparent at
sight, and is also proved by very easy and certain chestcal tests. The equipment is relatively cheap, but a
small as cunt of labor is required, and very little testnical supervision is necessary.

Plant Regulred:

The phant necessary for treating podes by the Boncherie process consists of a tank of the copper sulphate solution raised on a tower or other support at a sufficient elevation to force the selution through the poles after a suitable apparatus communicating with the elevated tank has been connected at the butt of each pole. In order to supply the reservoir solution tank on the turns with additional quantities of the preservative, a mixing tank is set up at the foot of the tower. Here the proper process formating the treating solution. A hand pump or one rem by each electric motor is generally installed to carry the solution electric motor is generally installed to carry the solution

from the mixing tank to the elevated storage tank. It is of course necessary that the tanks, pumps, and piping be made of material that will not be attacked by the copper sulphat. The elevation of the storage tank is generally the same as the length of the longest pole to be treated.

A lead pipe runs from the elevated storage tank to a general supply pipe running the length of the skidways and from this the rubber tube is fitted with a hollow wooden pin which is either inserted into a solid block of wood, which acts as a stopper when no poles are being treated, or into the treating device clamped on the butt of each pole.

In order to force the fluid from one end of the pole to the other it is necessary to use an inexpensive device which may be fastened to the butt end of the pole. This part of the equipment consists of a solid wooden section a little larger than the butt end of the pole, generally made of one piece of oak or elm planking reinforced by a small strip of wood, the notched ends of which project on both sides of the wooden butt plate. The plate is held in position on the end of the pole by means of two iron pins, one of which is bent at right angles and sharpened in order that it may be driven firmly into the pole, while the other end which engages the notched strip of wood previously mentioned, is threaded and carries a washer and nut. In using this device, a circle of packing or a vulcanized rubber ring is placed between the wooden disc and

For the mixing sank to "the drawed storage bank. It is of course newscarry that her tasks, pumps, And piping be made of material that will not be attached by the copper authors. The elevation of the storage whik he senerally the same as the length of the bongest bole to be treated.

A lead pipe muse from the elevated atorage tank to a general supply page running the length of the skidways and from this the rubbet tube is fifted with a hollow wooden pin which is sither inserved the solid block of wood, which as as a settper when he poles are being treated, or that the treating device of those on the being treated, or that the treating device of those on the

In order to force the fluid frick one end of the pole to the other it is necessary to wee an inexpensive device which may be farened to the buit end of the pole. This part of the equipment consists of a solid dociden Section a little larger than the butt end of the pole, generally made of one piece of cak or classication religious of by a small strip of wood, the netched ends of which project on both sides of the wooden butt plate. The plate is held in position on the end of the pole by means of two from plans, one of which is bent at right angles and sharpened in crear that it may be drived firmly into the pole, will be previously mentioned, is threaded and sharpened a washer and mut. In using this device, a situle of packing of a Vill-capital rubber rice is placed between the wooden died sharpened and rubber rices is placed between the wooden died sharpened and such as vill-capital rubber rices is placed between the wooden died sharpened and such as vill-capital rubber rices is placed between the wooden died sharpened and section of a vill-capital rubber rices is placed between the wooden died sharpened and section of a vill-capital rubber rices is placed between the wooden died sharpened and section of a vill-capital rubber rices is placed between the wooden died sharpened and section of a vill-capital rubber rices is placed between the wooden died sharpened and section of the wooden died sharpened and sharpened and section of the wooden died sharpened and sh

the butt of the pole in such a manner as to form a chamber at least 1/2" deep between the end of the pole and the disc. The pins carrying the washer and nut are inserted in the notches of this butt equipment with their sharpened ends driven deep into the pole. The nuts are then screwed up very tightly, making the narrow chamber between the pole and disc practically water-tight. There is a small hole through the wooden plate and into this the hollow wooden piece at the end of the rubber tubing is inserted. This establishes the connection between the elevated storage tank and the fluid-tight chamber at the butt of the pole.

Process of Treatment.

The plant should be located on a level area and in case about 7,000 poles a year are to be treated, it is usual to have a space of about 55,000 square feet or an area 330 feet long by 165 feet wide. Such plants have a capacity of about 25 to 50 poles a day. The plants must, of course, be located near the place where the poles are cut.

For this reason the treatment of poles must be commenced within a very few days of the time of cutting, the length of time depending upon the season of the year. During the summer, treatments must begin within 3 or 4 days, while in the winter time they need not commence

the butt of the pele in such a ranner as to tom a chamber at least 1/2" doep between the end of the pele and the district pins carrying the washer and not are inserted in the notions of this butt equipment with their sharpened ends driven desp into the pole: The nuts are then sorewed up very tightly, making the narrow chamber between the pole and disc practically waserstight. There is a small hole through the wooden plate and into this this hole piece at the end of the rubber thing is the hellow wooden plate and of the rubber thing is the hellow wooden and and of the rubber thing is the hellow wooden sank and the connection between the elevated storage sank and the finished the connection between the elevated storage sank and the tiluid-tight chamber at the butt of the pole:

Process of Transmit.

The plant shebld be located on a level area and in case about 7,000 poles a rear are to be treated; it is usual to have a space of about 35,000 equare feet er an area 350 feet long by 155 feet wide: Such plants have a capacity 8f about 25 to 50 poles a day: The plants must, of coarse; be located hear the place where the poles are cut:

For this reason the tradition of poles must be the mended within a very few days of the time of cutting, the longth of time depoinding upon the Beason of the Ferri. During the secons, tradition within 3 8F 4 days, while in the Winter time they had not combands.

must have seasoned as little as possible, retaining their normal quantity of sap and water. If any checks develop on the sides of the poles or through the bark the pole is in unsatisfactory shape for treatment, since the treating fluid may escape through these breaks. Further, if part of the sap has been lost through seasoning, it is found that the treatment is apt to be unsatisfactory through the pole. Therefore, the poles are hauled from the woods to the treating skidways as soon as possible after cutting, taking precautions not to injure the bark while transporting them since the bark is left on during the treatment.

The poles are placed on the treating skidways in a single even layer, the skids being so placed that there is a slight incline from the bottom of the pole toward the top. It is specified that the skids must be of sound, peeled timber, and must be removed as soon as they show signs of decay. A section of the butt of each pole is cut off in order to give a fresh and smooth surface for the connection of the apparatus to the pole. The butt of each pole is immediately fitted with the butt plate and connected with the large supply pipe running along the length of each skidway and described in the preceding pages.

There is some loss of preservative fluid at first, but this gradually lessens. Within three or

nest have seasoned as little as prosting in the police normal quantity of sap and water. If any checks develop on the sides of the poles or through the bark the pole is in unsatisfactory shape for treatment, size the treatment is further, if is in unsatisfactory shape for treatment, size the treatment, if part of the sap has been lost through seasoning, it is found that the treatment is apt to be unsatisfactory through the pole. Therefore, the poles are hauled from the woods to the treatment is as soon as possible after cutting, taking recentions not to injure the bark while transportations where the bark while transportations then the bark while transportating them where the bark while transportating them where the bark while transportating them where the bark is left on during the treatment.

The poles are placed on the treating skidways in a single even layer, the skids being so placed that there is a slight incline from the bottom of the pole toward the top. It is specified that the skids must be of sound, peeled timber, and must be removed as soon as they show signs of decay. A section of the butt of each pole is out off in order to give a fresh and smooth surface for the opiniseijon of the apparatus to the pole. The butt of each pole is immediately fitted with the butt plate and connected with the large supply pipe running along the length of each of idney and described in the preceding pages.

There is some loss of preservative fluid at first, but this gradually lessens. Within three or

four days the copper sulphate begins to drip from the top end of the pole. In order to insure a thorough treatment this is allowed to continue for several days longer or until the solution lost at the top of the pole is of the same composition as that injected. The entire time for treating the poles may require a week or 10 days. No attempt is made to recover any of the copper sulphate which is lost in the drip from the top of the poles. In fact, the French specifications expressly prohibit its use in further operations. At the end of the week or ten days the top end of the pole is a very green copper sulphate color.

The solution which is used for this treatment consists of 1 kilogram of copper sulphate to 100 kilograms of water. This chemical must be crystalized and must not contain more than 1 per cent of foreign matter, while the strength in pure copper must not be less than 24-1/2 per cent. The height of the surface of the liquid in the elevated tank varies according to the maximum length of the pole which it is proposed to treat at the plant. The French practice is from 6 to 6-1/2 meters for poles 6-1/2 meters long, and 10 meters for poles up to 12 meters long, and about 12-1/2 meters for poles 15 meters long.

After treatment the poles are seasoned for 30 days with the bark on, permitting the solution to work

four days the capper subphase begins to drip from the top end of the pole. In order to insure a thorough treatment this is allowed to sontings for several days longer or until the solution lost at the top of the pole is of the same composition as that injected. The antire time for freating the poles may require a week or 10 days. No attached is made to recover any of the copper sulphase which is lost in the drip from the top of the poles. In fact, the French specifications expressly prohibit its use in further operations. At the end of the week or ten days the top end of the poles or ten days the top end of the poles or ten days the

The solution which is used for this treatment semplats of 1 kilogram of copper sulphate to 100 kilograms of water. This chamical must be crystalized and must not osntain more than 1 per cent of foreign matter, white the strength in pure copper must not be less than 24-1/2 per cent. The height of the surface of the liquid in the elevated tank varies according to the maximum length of the pole which it is proposed to treat at the plant. The Trench practice is from 6 to 6-1/2 maters for poles 6-1/2 meters long, and 10 meters for poles up to 12 meters long, and about 12-1/2 meters for poles.

After treatment the poles are seasoned for 30 days with the tark on, permitting the solution to work

within the pole. If the bark is removed timediately, the poles are apt to take on an undesirable dark or black offer. At the end of the 50 days, the bark is removed from the poles and the top of each is pointed, cutting away from 6 to 12 inches of wood at that end. The freshly exposed surface at the top of the pole is then tested by the Government inspectors with a chemical reagent which gives a pink or reddish-brown color to the treated wood. (90 grams potassium ferrocyanide to 100 liters of water). From this color it is then possible to tell whether the treatment is satisfactory. Further, in order to be sure that the treatment is even and that the poles were not held too long before the treatment began, the Government inspectors have the right to cut up five poles per thousand and reject the entire lot if one of the five poles is below the requirements.

After the poles are accepted they are stamped with initials or marks indicating Government ownership and the name of the contractors who did the treating; also the date. The contractors must guarantee the poles for five years beginning with the first of January following the acceptance of the poles.

After the poles are accepted they are piled in high open piles for further seasoning, as shown in the photograph.

per sent.

within this pole. If the bank is removed amountary, the poles are apt to take on an undestrable dark or black ofter. At the end of the 50 days, the bank is removed from the poles and the top of each is pointed, cutting away from 5 to 12 inches of wood at that end. The freehly exposed autabace at the top of the pole is then tested by the Covernance inspectors with a chemical reagent which gives a pink or reddishabitour coldy to the treated wood. (90 grams potassium ferrocyanide to 160 liters of water). From this coler it is then possible to tell whether the treatment is sate its gettery. Further, is order to be sure that the treatment is even and that this poles were not held too long before the cut up five poles he thousand had reject ore have the right to out up five poles is balow the requirements.

After the poles are accepted they are stamped with initials of marks indicating Covernment ownership and the name of the contractors who did the treating; also the date: The contractors must guarantee the poles for five years beginning with the first of January Tollowing the acceptance of the poles.

After the poles are accepted they are piled in high open piles for further scarbains; as shown in the photograph.

Specifications.

The specifications governing poles treated by the Boucherie process for the French government include the following provisions:

Contracts for treated poles are made with the various companies supplying such material after competitive bids have been obtained.

In general only comiferous species of wood may be used, such as pine, fir, spruce, and larch, while the contract may specify only pine or fir. American white pine and Austrian pine, variety larico, are specifically excluded. Maritime pine which has been bled for turpentine may also be used, provided the exposed surface is not more than two feet long. No fire-killed trees can be used. Poles must be cut from healthy trees and the diameter of the heart-wood at the top of the pole must not exceed two-thirds of the top diameter. The contract specifies the sizes and the percentage of each size required, giving the length of the pole, its circumference at 1 meter from the butt end and at the top.

The solution used in treating the poles shall consist of 1 kilogram of copper sulphate for each 100 liters of pure water. The salt must be in the crystallized state and must not contain more than 1 per cent of foreign matter. The strength of the crystallized copper sulphate in pure copper must not be less than 24.5 per cent.

Specifications.

The specifications governing poles treated by the Boucherie process for the French government include the following provisions:

Contracts for treated poles are made with the various companies supplying such material after competitive bids have been obtained.

In general only coniferous species of wood may be used, such as pine, fir, spruce, and larch, while the contract may specify only pine or fir. American white pine and Austrian pine, variety larico, are specifically excluded. In time pine which has been bled for turpentine may also be used, provided the exposed surface is not more than two feet long. No fire-killed trees that be used. Poles must be out from healthy trees and the dismeter of the neartime to diameter. The contract specifies the sides and the top diameter. The contract specifies the sides and the pole, its circumference at 1 meter from the butter of and at the top.

The solution used in treating the poles shall consist of 1 kilogram of copper silphate for each 100 liters of pure water. The salt must be in the crystall lized state and must not contain more tidin 1 per cent of foreign matter. The strength of the crystallized of per sulphate in pure copper must not be less than 24.5

Provisions are induded for a minimum height of the reservoir of the solution above the poles, which, of course, controls the pressure under which the solution is applied. In general, this height equals the length of the poles to be treated, except in the case of very long poles when the height of the reservoir is proportionally somewhat less. The solution must be injected from the butt end of the pole and must penetrate the entire pole in a uniform manner. The Government reserves the right to out up any five poles selected from each thousand treated in order to see whether the penetration is satisfactory. If one pole out of the five selected is found to be improperly treated, the entire allotment may be rejected.

Thirty days after the poles are treated, but not sooner, they shall be peeled, shaved, and pointed at the top end. All refuse must be removed from the neighborhood of the skidways. The skidways must be of sound barked wood and must be replaced by the contractors at the first sign of decay.

For failure to comply with any of these provisions the contractor subjects himself to the possibility of the refusal of all poles which have been treated or which are being treated. The Government will pay for not exceeding 500 of the test poles which have been destroyed, irrespective of the total number of poles in the contractor's allotment. The remaining poles destroyed for inspection purposes shall be paid for by the contractor.

Provincent and the for a minimum height of the reservoir of the solution above the poles, which of apolied. In general, this height equals the length of the poles to be treated, except in the case of very long poles when the neight of the reservoir is proportionally somewhat less, The selution must be injected from the butt end of the pole and must penetrate the entire pole in a miforn manner, The Gevenment reserves the right to out a any five poles selected from each thousand treated in under to see whether the pensityation is satisfactory. *** 5 1 7 1 7 1 7 1 1 1 1 1 1 pole out of the five salected is found to be improperly treated, the entire allotment may be rejected. ection files in

Thirty days siter the poles are treated, but bornood of they stiduays, . The skidways must be of sound -- 1 3 W - 2 4 - 1 1 - 1 barred mood and mast be replaced by the contractors at the . Vingaboko mula teriti

ofor fallure to comply with any of these provistone the contractor subjects himself to the posmibility Han L of the infused officell peles which have been treated or The deverage treated. The deverament will pay for not Exclassing 560 of the test poles which have been destisted, trablor's allocate The remaining poles destroyed for in

......

In case the treating yard is more than three killometers from any habitable place, the contractor must provide transportation as often as 4 times per day, if required, to Government inspectors. Special provisions
of a precautionary nature are also included in each contract according to the peculiar circumstances. The contractor shall be responsible for the perfect preservation of
the treated poles for five years from the first day of
January following the delivery of the material to the Government.

Cost. in 50 representative lines in France under poor, and

A plant having a capacity of about 20,000 poles a year can be built in France for 1200. Copper sulphate is worth about 4-1/2 cents a pound in that country and it can probably be obtained cheaper in the United States if used in quantities. The cost of treating poles, including handling, runs from 50 to 80 cents for poles from 22 to 35 feet long.

Value of the Treatments.

Pine poles treated with copper sulphate last from six months to more than 25 years according to the character of the soil in which they are placed. But little is gained if the poles are in situations unfavorable to the treatment. Very wet locations, soils containing lime, and sandy soils are to be avoided.

In ourse the treating partit is, more than three hilonation from any hubitable place, the contractor much prowide transportation as often as 4 times per day, if required, to Covernment inspectors. Special provingons
of a precautionary nature are also inalled in each contractor according to the psculiar circumstances. The contractor shall be reappasible for the partiest day of
the treated pales for five years from the first day of
facturary following the delivery of the paterial to the Cov-

CCBt.

A plant having a capacity of about 20,000 poles a year can be built in France for 1200. Copper sulphase is worth about 4-1/2 cents a pound in that country and it can probably be obtained cheaper in the United States if used in quantities. The cost of treating poles, includating handling, runs from 50 to 80 cents for poles from 22 to 55 feet long.

Value of the Treatments.

Pine poles treated with copper sulphate lest from six months to more than 25 years according to the character of the soil in which they are placed. But little is gained if the poles are in situations unfavorable to the treatment. Very wet locations, soils containing lime, and sandy soils are to be avoided.

age life of their poles treated with this preservative at about 18 years in soil adapted to the treatment.

The average life secured in Germany, as shown elsewhere in this report, is 11.7 years. But this figure averages all conditions and grades of copper sulphate treatment. It is well understood that poles treated with zinc chloride should not be set in swamps but other and analogous conditions in the soil especially detrimental to copper sulphate have in many cases been disregarded

The following statement shows the average life of poles in 30 representative lines in France under poor, medium and good condition, and the character of the soil in which they were placed:

a portable outfit consisting mainly of two or more barrels containing the solution slump from a tree by block and backle and grab books, being raised high enough to secure the require

and grab hocks, being raised high enough to secure the require

some exportence approximately the right amount of solution for the skidway could be left in the barrels and no further

attention given the treating until desired at a later visit.

The experiments should determine:

1. Adaptability of western conifers, abundant on the

Wattonal Porests, to treatment by the Boucharie process for

2. The various preservatives that may be adapted to

the process

French officials state that they find the average life of their poles treated with this preservative to about 18 years in soil adapted to the treatment.

The average life secured in Gengary, as shown elsewhere in this report, is 11.7 years. But this figure averages all conditions and grades of copper sulphate treatment. It is well understood that poles treated with zinc chloride should not be set in swamps but other and analogous conditions in the soil especially detrimental to copper sulphate have in many cases been disregarded.

The following statement shows the average life of poles in 50 representative lines in France under poor, medium, and good condition, and the character of the soil in which they were placed:

Adaptability of the Process to American Conditions.

It is possible that experiments will demonstrate that under certain conditions the Boucherie process with copper sulphate or other preservatives may prove valuable in America. The National Forests appear to offer an exceptionally good field for trying out the process. The preservative, whether copper or other salts, can be transported long distances at a relatively small cost, an outfit can be devised that is not only very simple but casily moved from place to place, and the men in direct charge of the work are required to give a minimum amount of time to it, and to possess a minimum amount of technical knowledge to treat the poles. Poles can be skidded in lotsof 25 along the proposed line and treated immediately by a portable outfit consisting mainly of two or more barrels containing the solution slung from a tree by block and tackle and grab hooks, being raised high enough to secure the requisite pressure at the ground end of the treating tubes. After some experience approximately the right amount of solution for the skidway could be left in the barrels and no further attention given the treating until desired at a later visit.

The experiments should determine:

- l. Adaptability of western conifers, abundant on the National Forests, to treatment by the Boucherie process for poles, posts, and other uses.
- 2. The various preservatives that may be adapted to the process.

Adaptability of the Process to American Conditions.

It is possible that experiments will demonstrate that under certain conditions the Boucherie process with copper sulphate or other preservatives may prove valuable in America. The Mational Forests appear to offer an oxceptionally good field for trying out the process. The preservative, whether copper or other salts, can be transported long distances at a relatively small cost, as sutfit can be devised that is not only very simple but easily moved from place to place, and the men in direct ouarge of the work are required to give a minimum amount of time to it, and to possess a minimum amount of ted pical knowledge to treat the poles. Poles can be skidded in lotsof 25 along the proposed line and treated immediately by a portable outfit consisting mainly of two or more barrels containing the solution slung from a tree by block and tackle and grab hooks, being raised high grough to secure the requisite pressure at the ground end of the treating tubes. After some experience approximately the right amount of solution for she skidway could be left in the barrels am no further attention given the treating until desired at a later visit. The experiments should determine:

1. Adaytability of western confiers, abundant on the Mational Forests, to treatment by the Boucherie process for poles, posts, and other uses.

2. The various preservatives that may be adapted to

the process.

- 3. Means for ascertaining the extent of the treatment that a pole has received with each preservative.4. The factors influencing the treatment of each
- species such as:

 (a) Pressure of the solution at the point of application, or the height of reservoir

mere callet tanks; thore are favorable for the applica-

- (b) Effect of excessive hot or cold weather;
- (c) Effect of holding poles before treatment one to ten or more days after cutting;
 - (d) Practicability of water storage of poles between cutting and treatment.
- 5. Recovery and use of preservative ordinarily wasted in this process.
- 6. Specifications covering the treatment of American species by the Boucherie process.
- 7. Design of apparatus especially adapted to use on the forests.
- 8. The increased service resulting from treatments through a record of all poles set in lines.

Present Status of Experiments.

Arrangements are now being made by C. Stowell Smith, Assistant District Forester in Charge of Products in District 5, to determine the value of the process for certain pole timbers of the National Forests in that district. The experiments will be conducted on the Eldorado National Forest this summer.

- 5. Means for assertaining the except of the treatment that a pole has received with each preservative.
 - .4. The factors influencing the treatment of each
 - (a) Pressure of the solution at the point of application, or the height of reservoir tanks;
 - (b) Effect of excessive hot or ould weather;
 - (c) Effect of holding goles before trestment one to ten or more days after outting;
 - (d) Practicability of water atorage of poles between cutting and treatment.
 - 5. Recovery and use of preservative, ordinarily wasted in this process.
 - 6. Specifications covering the treathent of American species by the Boucherie process.
 - 7. Design of apparatus especially adapted to mise
 - 8. The increased service resulting from treatments through a record of all poles set in lines.

Present Status of Experiments.

Arrangements are now being made by G. Stewell Smith, Assistant District Forester in Charge of Products in District 5, to determine the value of the process for certain pole timbers of the Pational Forests in that district. The experiments will be conducted on the Eldorado National Forest this summer.

If the preliminary investigation warrants it, further experiments should be made on other Western forests, especially those of the Southwest and the central West where the use of creosote is practically prohibited by its high cost, and in the Southern States of the East where climatic conditions are favorable for the application of the treatment during the entire year and where the treatment of the entire pole is now necessary.

If the preliminary investigation warfants it, further experiments should be made on other Western forests, especially those of the Southwest and the dential vest where the use of Sreseotically prohibited by its high cost, and in the Southern States of the East where elimits conditions are favorable for the siplication of the ticatment during the entire year and where



UNIVERSITY OF CALIFORNIA LIBRARY, BERKELEY

THIS BOOK IS DUE ON THE LAST DATE STAMPED BELOW

Books not returned on time are subject to a fine of 50c per volume after the third day overdue, increasing to \$1.00 per volume after the sixth day. Books not in demand may be renewed if application is made before expiration of loan period.

APR 2 1930

426727

UNIVERSITY OF CALIFORNIA LIBRARY

